

**ACTION PLAN FOR EUB DECISION 2004-056**

**BUMPER DEVELOPMENT CORPORATION LTD. (BUMPER)  
REVIEW OF WELL LICENCE NO. 0287658  
DAVEY FIELD**

	ACTION ITEM	REQUIRED ACTION/COMMENTS	REFERENCE: D 2004-056	EUB PROCESS TO ENSURE FOLLOW-UP	STATUS & EVIDENCE
1	Cap Access Road	The Board requires Bumper to cap the crown of the access road with 7 centimetres of gravel. Bumper must cover the shoulders of the access road with topsoil and plant vegetation similar to that surrounding the road. Bumper must notify the EUB upon completion, which must be no later than October 1, 2004.	P. 8, Appendix 2	Require confirmation from Bumper that access road capped	<p><i>Complete.</i></p> <p>September 27, 2004. Board received confirmation that the road was capped. A May 2005 field inspection verified that the access road had been capped and that soil and vegetation had been provided to the shoulder of the access road.</p>
2	Soil, water and forage testing plan	Bumper must retain an expert on soil, water, and forage testing and submit a plan to the EUB for review and approval by September 15, 2004. The plan must include a program for soil, water, and forage testing for a one-year period. A copy of the plan must be provided to the Normans and Mr. James. Upon approval by the EUB, Bumper must implement the one-year plan immediately and provide the expert's report and recommendations for future testing, if necessary, by December 31, 2005.	P. 8, Appendix 2	EUB to review and approve plan then advise Bumper to implement plan.	<p><i>Complete.</i></p> <p>September 14, 2004. Board received report from Bumper.</p> <p>September 27, 2004. Board review of report complete.</p> <p>October 26, 2004. Board approved the methodology for soil, water, and forage testing submitted by Komex International Ltd. (Komex), on behalf of Bumper.</p> <p>December 7, 2005. Received final report from Komex which contained no recommendation for further testing at the site.</p>