ACTION PLAN FOR ERCB DECISION 2009-059

STANDARD ENERGY INC.

APPLICATION FOR TWO WELL LICENCES, GRANDE PRAIRIE FIELD

	ACTION ITEM	REQUIRED ACTION/COMMENTS	Decision 2009-059	ERCB PROCESS TO ENSURE FOLLOW-UP	STATUS & EVIDENCE
1	Grande Prairie Field Office site inspections	ERCB field inspectors will be conducting an inspection of the 13-20 lease site, 7-20 lease site, and 14-30 lease site after the issuance of the licences to ensure that the issues with respect to oil staining and oil leaking from stored pipes and oil filters have been rectified. Furthermore, ERCB field inspectors will be conducting a follow-up inspection of the lease sites in six months to ensure that the issues do not recur and have not been neglected. The ERCB field inspectors will be reporting back to the Board after the completion of each inspection.	Section 4.3 paragraph 13 page 7	Grande Prairie Field Office to issue inspection summary to the parties who participated at the hearing.	Completed - Final field inspection summary report prepared and sent to the hearing participants. 17-Dec-09 - Field inspection summary report prepared and sent to the hearing participants. Date Evidence Received: 31-May-10

The conditions imposed in approvals/licence(s) are monitored by the Alberta Energy Resources Conservation Board (ERCB). The ERCB has developed a process whereby an action plan is developed internally to ensure that ERCB staff monitor conditions arising from decision reports for compliance. The conditions are managed in an action plan that is updated quarterly with statuses of conditions. The action plan defines the action required, timeframes for completion, and a summary of the evidence provided to confirm a condition was met. For more information, please contact the Action Plan Administrator at (403) 476-4783.

Tuesday, June 01, 2010 Standard Energy Inc. 2009-059 Page 1 of 1